

EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|------|---|--|------------------|---------|------------------|
| L1 | 624 | vehicle same meter same (diagnos\$5 or fault\$5) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:00 |
| L2 | 275 | (fault near6 codes)and (LCD same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:38 |
| L3 | 2 | 1 and 2 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:38 |
| L4 | 889 | ((fault near6 codes)same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:39 |
| L5 | 12 | 1 and 4 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:39 |
| L6 | 36 | ((fault near6 codes)same display\$4)and (vehicle same meter) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:47 |
| L7 | 1 | (fault near6 codes)same display\$4 same (vehicle same meter) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 10:47 |

EAST Search History

| | | | | | | |
|-----|-----|--|--|----|-----|------------------|
| L8 | 13 | ("5327344" "5345383" "5347260" "5361059" "5371487" "5374917" "5453939" "5648898" "5819201" "5949330" "6212483" "6320497" "6334085").PN. OR ("6766231").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2007/04/17 10:53 |
| L9 | 11 | ("4109235" "5063513" "5880710" "5884243" "5949330" "6006146" "6112150" "6134488").PN. OR ("6320497").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2007/04/17 10:57 |
| L10 | 36 | (vehicle same meter) and CAN and ((fault near5 codes)same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:01 |
| L11 | 802 | (vehicle same meter) and CAN and (control same unit same radio) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:03 |
| L12 | 111 | (vehicle same meter) and CAN and ((control same unit) near5 radio) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:03 |
| L13 | 1 | 10 and 12 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:03 |
| L14 | 14 | (vehicle same meter) and CAN and ((control same unit) near5 radio) and ((fault or diagnos\$5)same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:06 |
| L15 | 149 | (vehicle same meter) and (CAN same network)and ((link\$4 or connect\$4)same radio) and ((fault or diagnos\$5)same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:07 |

EAST Search History

| | | | | | | |
|-----|------|--|--|----|----|------------------|
| L16 | 23 | (vehicle same meter) and (CAN same network)and ((link\$4 or connect\$4)same radio) and ((fault or diagnos\$5)same codes same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:09 |
| L17 | 2359 | (vehicle same meter) and (CAN same network) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:09 |
| L18 | 2580 | (vehicle same meter) and (CAN same controller) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:09 |
| L19 | 19 | (vehicle same meter) and (CAN same controller)and ((fault near5 codes)same display\$4) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:11 |
| L20 | 57 | (vehicle same meter) and (CAN same controller)and ((fault near5 codes)) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:26 |
| L21 | 1098 | (vehicle same meter) and (CAN or (control near5 area near5 network))and (radio same (connect or link\$4)) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:28 |
| L22 | 40 | (vehicle same meter) and (CAN or (control near5 area near5 network))and (radio same (connect or link\$4))and (fault near5 codes) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:34 |

EAST Search History

| | | | | | | |
|-----|--------|---|--|----|-----|------------------|
| L23 | 166 | (vehicle same meter) and (CAN near5 network)and (radio near5 link) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:35 |
| L24 | 70 | (vehicle same meter) and (CAN near5 network)and (radio near5 link)and (CAN near5 controller) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:42 |
| L25 | 124 | (vehicle same meter) and (CAN near5 network)and (engine same control)and (braking same control)and (steer\$4 same control) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:43 |
| L26 | 35 | (vehicle same meter) and (CAN near5 network)and (engine same control)and (braking same control)and (steer\$4 same control)and (radio near5 link) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2007/04/17 11:45 |
| L27 | 173579 | "701"/\$.ccls. or "340"/\$.ccls. or "342"/\$.ccls. or "180"/\$.ccls. | USPAT | OR | OFF | 2007/04/17 11:45 |
| L28 | 39 | 25 and 27 | USPAT | OR | OFF | 2007/04/17 11:45 |
| L29 | 53 | ("4777585" "4825367" "4829434" "4922428" "4930084" "5019979" "5036730" "5036936" "5048100" "5058180" "5067374" "5099428"). PN. OR ("5162997").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2007/04/17 11:50 |